

**PEARSON STREET & INNER DRIVE**

**Existing Conditions**

- The ground level experience is dominated by roadway and vehicles
- While the lake can be seen, accessing it is difficult and for some users impossible
- The design of inner Lake Shore Drive makes northbound transit access very difficult – with almost no space between inner and outer drive for sidewalks or bus boarding



**Potential Future Condition**

- The outer lanes of NDLSD are placed below-grade at this location, providing direct pedestrian and bike connections from the urban edge to the lakefront
- Additional space is provided to allow for streetscaping, trees and sidewalks on both sides of inner NDLSD
- New signalized intersections on inner Drive with clearly marked crossings, and improved wayfinding signs will help connect the urban edge to the lakefront

