


North Lake Shore Drive *Existing Conditions* INFRASTRUCTURE REPORT CARD



LEGEND

Structure Location	Structure Appraisal
Orange square	MS Meets Standards
Green hexagon	SD Structurally Deficient
Yellow hexagon	FO Functionally Obsolete
Red hexagon	ADA Meets ADA Requirements
Red hexagon with slash	Does not meet ADA Requirements

Structure Condition*

- Good (Green hexagon)
- Fair (Yellow hexagon)
- Poor (Red hexagon)

Shoreline Protection

- Roadway/Lakefront (Red line)
- Trail Flooding (Yellow line)
- Deteriorated (Purple line)
- Shoreline Revetment (Blue line)

Americans with Disabilities Act (ADA) Compliance**

- Meets ADA Requirements (Blue circle with ADA)
- Does not meet ADA Requirements (Red circle with slash and ADA)

Notes:
* Structure Condition is based on lowest condition rating for Deck, Superstructure, and Substructure.
** ADA Compliance applies to structure and approach pathways.



Definitions
Structurally Deficient - important load carrying elements were rated to be in poor or worse conditions due to deterioration or damage.
Functionally Obsolete - do not meet current standards for deck geometry, load carrying capacity, clearance or approach roadway alignment or which could not adequately serve user demands.